

NORTH BOEING FIELD SPILL REPORT

BCAG
RENTON DIVISION

DATE: 11-17-92
BY: M. BLACK

LOCATION OF SPILL: B-318 BLDG - CHILLED ROOM
DATE OF SPILL: 11-16-92 TIME OF SPILL: 1600 AM
PM

SPILL REPORTED BY: Gene BARNHOLDT ORGN: B-7000
PHONE: 655-1909 TIME: 1545 AM
PM

MATERIAL SPILLED: METHYLENE CHLORIDE ESTIMATED QUANTITY: 1/2 GAL + 4 GAL
EVAPORATED: ☐ (RQ) REPORTABLE QUANTITY: YES ☐ NO ☐
CONTAINED ON SITE: ☒ SPILLED TO DRAIN: # SPILLED TO SURFACE WATER ☐

REGULATORY AGENCIES NOTIFIED: YES ☐ NO ☒ TIME: NOTIFIED BY:

WHICH AGENCIES AND PERSONS:
BOEING OFFICES NOTIFIED: DIRECTOR OF FACILITIES ☒ PUBLIC AFFAIRS ☐
CORPORATE INSURANCE ☐ ENVIRONMENTAL AFFAIRS ☒ PUBLIC RELATIONS ☐

CAUSE OF SPILL: LEAKY GASKET

RESPONSIBILITY FOR SPILL: NONE

ACTIONS TAKEN AND BY WHOM: REPAIRED BY HAZ. MAT. TEAM
METHYLENE CHLORIDE DISPOSED OF AS HAZARDOUS WASTE.

FOLLOW-UP ACTION REQUIRED: REPAIR LEAK

DISTRIBUTION:		
L.M. BABICH III	R-1150	63-01
T. HAMPER	R-6410	17-MA
H. PLATTEBORZE	R-6101	17-MA
T. WESTALL	R-6001	63-01
J.E. STEVENS	4-1720	17-WA